

Ship Name: **CORAL GABLES**

IMO Number: **8317459**

Date Detained: **06/10/2003**

Port: **Port Everglades, Florida**

Ship Type: **Tankship (Not Specified)**

Flag: **Panama**

Class Society: **Honduras International Naval
Surveying and Inspection Bureau**

Company(s): Owners, Operators or Managers
Grace Tanker Limited
Denistank Limited

Deficiencies: Code - Category
0220 - Certificates of competency

0710 - Fire prevention

0610 - Lifeboats

**2545 - Reports/analysis of
non-conformities, etc.**

Description
**Some officers missing valid flag state
endorsements.**

**Engine Control Room does not meet
structural fire protection requirements.**

Port lifeboat inoperative.

**Identified major non-conformities in ISM
system. Vessel not following internal SMS
requirements. No evidence of company DPA
addressing vessel requests.**

Ship Name: **FOREST LINK**

IMO Number: **7129623**

Date Detained: **06/20/2003**

Port: **Mobile, Alabama**

Ship Type: **Ro-Ro-Cargo Ship**

Flag: **Panama**

Class Society: **Lloyd's Register of Shipping**

Company(s): Owners, Operators or Managers
Paper Sea A.S

Deficiencies: Code - Category
0220 - Certificates of competency

Description
**Vessel's stbd main propulsion engine is
damaged and inoperable. PSCO questions the
validity of the vessel's Ship Safety**

Ship Name: **H. F. SAHLMAN**

IMO Number: **8117201**

Date Detained: **06/10/2003**

Port: **Tampa, Florida**

Ship Type: **General Dry Cargo Ship**

Flag: **Saint Vincent and the Grenadines**

Class Society: **Lloyd's Register of Shipping**

Company(s): Owners, Operators or Managers
Carib Services International Ltd.
Carib Services Ltd.

Deficiencies: Code - Category
**0730 - Appliances (general
equipment)**

Description
Inoperable emergency fire pump.

Ship Name: **H.F. SAHLMAN**
IMO Number: **8117201**
Date Detained: **06/26/2003**
Port: **Tampa, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Saint Vincent and the Grenadines**
Class Society: **Lloyd's Register of Shipping**
Company(s): Owners, Operators or Managers
Carib Services Internatiional Ltd.
Carib Services Ltd.

Deficiencies: Code - Category
0230 - Number/composition
(manning)
0220 - Certificates of competency

Description
Invalid minimum Safe Manning Document.
Master unable to identify correct document.
Crew compliment not manned in accordance
with minimum Safe Manning Document. Crew
officers held invalid flag state licenses.

Ship Name: **HUAL TRAVELLER**
IMO Number: **8116908**
Date Detained: **06/09/2003**
Port: **Jacksonville, Florida**

Ship Type: **Ro-Ro-Cargo Ship**
Flag: **Norway**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
Hoegh Fleet Services AS

Deficiencies: Code - Category
0220 - Certificates of competency

Description
No endorsement from Flag State for Officers
licenses.

Ship Name: **KLIOMAR**
IMO Number: **8813568**
Date Detained: **06/05/2003**
Port: **San Francisco, California**

Ship Type: **Tankship (Not Specified)**
Flag: **Cyprus**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Stelmer Tankers
Kliomar
Kliomar LTD

Deficiencies: Code - Category
0615 - Rescue boats
1220 - Freeboard marks

Description
The designated rescue boat has a puncture
ththrough the outer shell of the upper canopy,
compromising the integrity of the vessel.
The validity of the vessel's Load Line
Certificate was called into question since three
separate load line markings are permanently
affixed and painted on the side of the vessel,
each of which is label with NKK. ABS issued

Ship Name:	MONTAN	Ship Type:	Bulk Carrier
IMO Number:	8218744	Flag:	Liberia
Date Detained:	06/05/2003	Class Society:	Germanischer Lloyd
Port:	New Orleans, Louisiana	Company(s):	<u>Owners, Operators or Managers</u> Montain Shipping Corporation Chartering & Marine Services

Deficiencies:	<u>Code - Category</u> 1420 - Cleanliness of engine room	<u>Description</u> Excessive fuel and oil on the machinery and in containments throughout the machinery space.
	1499 - Other (Prop. & Aux. Machinery)	The diesel oil purifier main supply pipe is leaking excessively and purifier space bilge is full of fuel oil.

Ship Name:	REGAL EMPRESS	Ship Type:	Passenger Ship
IMO Number:	5262835	Flag:	Bahamas
Date Detained:	06/19/2003	Class Society:	Bureau Veritas
Port:	Port Everglades, Florida	Company(s):	<u>Owners, Operators or Managers</u> Celebration World Cruises, Inc Imperial Majiesty Cruise Line, LLC

Deficiencies:	<u>Code - Category</u> 0610 - Lifeboats	<u>Description</u> Seven lifeboat davits compromised due to wastage. Two davits (boats 1 & 2) had wastage on the davit foundation and are out of service. The remaining 5 davits torque tubes were wasted and holded.
	0630 - Launch arrangt. for survival craft	Lifeboat #16 not capable of being launched due to fendering system; fendering system prevented it from being launched because they hit the deck rail.
	0680 - Embarkation arrangt. survival craft	Crew unable to satisfactorily launch the liferafts within the time require by SOLAS.
	2099 - Other (SOLAS Related Operational Def.)	The hotel manager's office has been modified or added not in accorance with the ship's fire control plan. (originally a technical space with dumb waiter and electrical installations)
	2099 - Other (SOLAS Related Operational Def.)	The tour guide reception desks, located in the main stairway, have been closed in with solid wooden shutters.
	2099 - Other (SOLAS Related Operational Def.)	Copy room on sun deck has been modified. Bulkhead between the audio room and technical locker has been cut and door has been replaced with a wooden bulkhead. The space is now a manned office space and is not in accordance w/ the fire control plan.
	1299 - Other (Load Lines)	Vessel is not marked with a C1 subdivision Loadline; vessel is only equipped with standard freight ship load Fresh Water and Summer Loadlines.
	0699 - Other (Life Saving Appliances)	Life jacket locker in main stairway must be emptied and permanently closed due to flammability concerns.

0915 - Signs indications	Signage throughout vessel missing. Install proper escape and lifesaving signage in accordance with SOLAS and IMO Resolution A.780 (18).
0710 - Fire prevention	Forty (40) fire screen doors were found discrepant; including doors unable to close, damage and doors not indicated on the bridge mimic panel.
1270 - Doors	Side shell openings not water /weathertight; two side shell doors showed light around the gasket sealing surface when in the closed/secure position.
0945 - Emergency lighting, etc	Transitional power is suspect due to missing batteries and dead end cables in the battery storage room.
0725 - Fixed fire extinguishing installation	Fire main holed in at least 5 places.
0945 - Emergency lighting, etc	Low location lighting is photo luminescent tape with no record of 5 year testing. Also, insufficient ambient light to satisfactorily maintain a charge on the tape in a number of areas.

Ship Name: SENATOR	Ship Type: Bulk Carrier
IMO Number: 9052329	Flag: Bahamas
Date Detained: 06/04/2003	Class Society: Nippon Kaiji Kyokai
Port: Portland, Oregon	Company(s): <u>Owners, Operators or Managers</u> Evalend Shipping Co. Sea Honour Marine S.A. Evalend Shipping Co. S.A.
Deficiencies: <u>Code - Category</u> 1795 - Other (Suspected Of Discharge Violation)	<u>Description</u> After discovery of an oil overboard valve stem during a re-inspection, and expanded MARPOL exam was complete. Found sufficient evidence of the dumping of waste oil/sludge from vessels waste oil system.

Ship Name: ST. PAULI	Ship Type: Tankship (Not Specified)
IMO Number: 9253478	Flag: Singapore
Date Detained: 06/08/2003	Class Society: Nippon Kaiji Kyokai
Port: Long Beach, California	Company(s): <u>Owners, Operators or Managers</u> Shenlong Maritime Maruta Industries Co. LTD.
Deficiencies: <u>Code - Category</u> 2020 - Fire drills	<u>Description</u> Crew unable to demonstrate proficiency in a satisfactory fire drill.